

In the Drawing:

As shown in the accompanying marked-up replacement sheet, please amend the drawings as follows.

Figure 5 has been amended to include numeral “114” to identify an interior side wall, numeral “116” to identify an exterior side wall, numeral “132” to identify a top edge, numeral “136” to identify a front edge and numeral “138” to identify a rear edge. Figure 5 has been also amended to clarify a top surface identified as numeral “124.”

Figure 6 has been amended to include numeral “114” to identify an interior side wall.

Figure 7 has been amended to include numeral “116” to identify an exterior side wall, numeral “132” to identify a top edge, numeral “136” to identify a front edge and numeral “138” to identify a rear edge.

Figure 8 has been amended to include numeral “112” to identify a front surface.

Figure 9 has been amended to include numerals “120, 122” to identify a rear wall and numeral “118” to identify opening. Figure 9 has been also amended to identify the opening.





Figure 10 has been amended to include numeral “124” to identify a top stanchion surface.

Figure 11 has been amended to include numeral “126” to identify a bottom stanchion surface.

Figures 80B and 81B have been amended to correct numeral “340” to numeral “350” to avoid using the same numeral “340” that also identifies four rectangular brackets.

The changes have been indicated in red and it is not believed to contain new matter.

Attachment: Replacement sheets





35/36

FIG. 80B

FIG. 80A





FIG. 81A

FIG. 81B





FIG. 82A

FIG. 82B

